

NASA/ESA Hex-Chrome Project

Technology Evaluation for Environmental Risk Mitigation
Principal Center

Matt Rothgeb


International Workshop on Environment and Alternative Energy

October 23, 2014

Kennedy Space Center, FL



Current NASA TEERM CrVI Projects:





NASA/ESA CrVI Alternatives - 3 Phase Project

Phase 1:

Screening of Conversion Coatings - COMPLETED

Phase 2:

- Screening of Primers NEARLY COMPLETE One Primer Remains in test
- Extended testing of Conversion Coatings STARTING in CY2014

Phase 3: - NOT STARTED YET

- Testing of best performing Conversion Coatings + Primers
- Testing of best performing Conversion Coatings + Primers + Topcoats

NASA

HCFCFE

Х

Partial List

Screening

- AlodineŒC2
- Corrlink**3**0A
- Deft@RECC
- x UMRICeCC
- x EONICoat
- x NANOMYTETC-4001
- x NANOMYTE®T-10®

HCFCFE

Pretreatments

- x Alodine 1600
- x Alodine559002
- x Iridite®NCP
- x Metalast HF
- x Metalast HF-EPA
- x Surtec 50
- x Surtec 50C

Phase 1

ESA/NASA

Screening

- p Alodine 2200s 24 added) 23 Control
- x Alodine 1600 15 control
- 1 p Alodine 160/161
- 2 p Alodine 5993 Plus
- 3 p Interlox5705
- 4 p MAP\silico
- 5 x AlodineŒC2
- 6 x Corrlink 30A
- 7 Deft®RECC
- 8 x UMRICeCC
- 9 x EONICoat
- 10 x XBond 24000 2
- 11 x NANOMYTETC-4001
- 12 x NANOMYTE®T-10?
- 13 r Alodine559002
- 14 r Iridite INCP
- 15 r Metalast⊞F
- 16 x Metalast HF-EPA
- 17 x Surtec**3**550
- 18 r Surtec 550C
- 19 n Surtec 550V



NASA/ESA Phase I Project Results & Overview of Next Phases

NASA/ESA (Phase 1) & HCFCFE Test Programs



Initial Screening Testing:

- ASTM B117 Salt Fog to Failure
- ASTM G85 Cyclic Corrosion (A5)
- Beachfront Exposure Testing
- Wet Tape Adhesion

Substrates:

- 2024 T3
- 7075 T73
- 6061 T6

Initial Results:

- All Passed Adhesion
- Cyclic Corrosion was inconclusive
- Beachfront Analysis was inconclusive
- ASTM B117 Results showed mixed and unexpected results







- Initial Screening testing results were mixed on known commodities (Controls and Approved Non-Chromes)
- Initial re-testing did not provide clear answers
- Decision made to spend effort on optimization of pretreatment application and panel preparation processes
- ≈ 5 Rounds of process optimization were conducted (Round considered major material or process change)



Round 1A

Substrates: 2024 / 2219 / 7075 / 6061 Cleaning: Scotch Bright + Ethanol



PROCESS 1

Cleaner


Chemetall-Oakite NST – (5% by volume)

Deoxidizer

 70% Nitric Acid/DI water = mixed 1:1 - agreed upon by stakeholder consensus

Process Optimization - Process 1







PROCESS 2

Cleaner


Specialty 740 (9 oz/gal)

Deoxidizer

 Specialty 982 (15% by volume) – currently being used by local plating shop

Process Optimization - Process 2





Process Optimization



RESULTS:

- Alodine 1200S
 - Failures on 2219 Expected
 - Failures on 2024 Not Expected (<168 Hours)
 - Passing on 6061 & 7075 336 Hours +

Metalast TCP

- Failures on 2219 Expected
- Passing on 2024 Expected 168 Hours (barely)
- Passing on 6061 & 7075 672 Hours +

Surtec 650 C

- Failures on 2219 Expected
- Failures on 2024 Not Expected (<168 Hours)
- Passing on 6061 & 7075 504 Hours +



Optimization Iterations

 5 Iterations were completed that incorporated a variety of substrates, cleaners and deoxidizers.

 12+ Months to complete optimization to stakeholder satisfaction





Round - 1B

- Focusing on hardest alloys to protect
 - 2024-T3
 - 2219-T8
 - 7075-T6
- Alodine 1200S alter contact times for deoxidizer
 {Specialty 982 (20% by volume) only} and Alodine bath
- Hexavalent chrome-free alternatives alter contact time for deoxidizer only
 - 70% Nitric Acid/DI water = mixed 1:1 agreed upon by stakeholder consensus
 - Specialty 982 (20% by volume) currently being used by local plating shop





Round 2

- Changing initial solvent cleaning process
 - Replace ethanol (200 proof) to methyl ethyl ketone (MEK)
- Eliminating the use of Scotch-Brite pads
- Eliminated Nitric Acid Deoxidizer
- Alloys:
 - 2024-T3
 - 5052-H32 (ADDED AS PART OF GSDOP)
 - 6061-T6 (ADDED AS PART OF GSDOP)





Round 3

- Changing initial solvent cleaning process
 - Replace ethanol (200 proof) to methyl ethyl ketone (MEK)
- Eliminating the use of Scotch-Brite pads
- Eliminated Nitric Acid Deoxidizer
- Alloys:
 - 2024-T3
 - 5052-H32 (ADDED AS PART OF GSDOP)
 - 6061-T6 (ADDED AS PART OF GSDOP)





Round 4

- Changing initial solvent cleaning process
 - Replace ethanol (200 proof) to methyl ethyl ketone (MEK)
- Eliminating the use of Scotch-Brite pads
- Eliminated Nitric Acid Deoxidizer
- Alloys:
 - 2024-T3
 - 5052-H32 (ADDED AS PART OF GSDOP)
 - 6061-T6 (ADDED AS PART OF GSDOP)





Round 5A

- Changing initial solvent cleaning process
 - Replace ethanol (200 proof) to methyl ethyl ketone (MEK)
- Eliminating the use of Scotch-Brite pads
- Eliminated Nitric Acid Deoxidizer
- Alloys:
 - 2024-T3
 - 5052-H32 (ADDED AS PART OF GSDOP)
 - 6061-T6 (ADDED AS PART OF GSDOP)





Round 5B

- Changing deoxidizer times for Turco Smut-Go NC
 - Brackets around previous Round (60 seconds)
 - 0s, 10s, 30s, 120s
- Only evaluating 2024-T3
- Removed Alodine 1200S
- Removed Surtec 650 C





Round 5C

- Tested only Alloy 2219 (limited quantity available)
 - Clad test Panels scrubbed with Scotch-Brite pads to a dull surface
 - Bare test panels; no Scotch-Brite scrubbing
- Tested only Surtec 650V



Summary of Phase 1 Project Results



HCFCFE

Screening

- x Alodine EC2
- x Corrlink30A
 - Deft**®**ECC
- x UMRICeCC
- x EONICoat
- x XBond 4000
- x NANOMYTETC-4001
- x NANOMYTE®T-10®

HCFCFE

Pretreatments

- Alodine 1600
- x Alodine \$5900
- x Iridite INCP
- x Metalast HF
- x Metalast HF-EPA
- x Surtec 50
- x Surtec 50C

Phase 1

ESA/NASA

Screening

- p Alodine 1200s 1added 13 Control
- x Alodine 1600 1 Control
- 1 p Alodine 160/161
- 2 p Alodine 3993 Plus
- 3 p Interlox 5705
- 4 p MAP\silico
- 5 x AlodineŒC2
- 6 x Corrlink**3**0A
- 7 p Deft®RECC
- 8 x UMRICeCC
- 9 x EONICoat
- 10 x XBond 24000 2
- 11 x NANOMYTETC-4001
- 12 x NANOMYTE®T-10?
- 13 r Alodine559002
- 14 r Iridite®NCP
- 15 r Metalast⊞F
- 16 x Metalast HF-EPA
- 17 x Surtec **3**50
- 18 r Surtec 550C
- 19 n Surtec 550V



Phase 2 Plans and Results to Date

Screening phase 2)

ESA/NASA

Screening T+PR

Alodine 2200S Koropon MAP\stilico MAP Silico MAP\stilico Deft 1084

MAP\stilico Hentzen 16708

MAP\silico PM820 Alodine5923Plus MAP\(\mathbb{S}\)ilico Alodine5923Plus + Deft1084

Alodine 3923 Plus + Hentzen 16708

Alodine 3923 Plus PM820 Metalast TCP MAP\silico Metalast[®]CP Deft1084

Hentzen 16708 Metalast[®]CP

Metalast[®]CP PM820 SurTec 550V MAP Silico Deft 1084 SurTec 550V

Hentzen 16708 SurTec 550V

SurTec 550V PM820

MAP Silico **NAVALCOAT** Alodine™923

Plus **NAVALCOAT** Metalast²CP + NAVALCOAT Surtec 550V **NAVALCOAT**

Substrate:

2024-T3

Testing:

- ASTM B117 Salt Fog
- Adhesion PATTI Jr.



Phase 22 ESA/NASA

Pretreatments

Alodine 2200S

Iridite 14-2

Metalast?TCP

MAP Silico

Alodine 5923 Plus

SurTec 550V

Substrates:

- 2024-T3
- 2024-T8
- 6061-T6
- 7075-T6
- 7075-T73

Testing:

- B117 Salt Fog NASA/ESA
- Humidity Exposure ESA
- Thermal Cycling ESA
- Adhesion X-Cut Tape NASA
- Resistivity ESA



Phase 2 - Test Data - CC+Primers Matrix


- PATTI Pull Complete
- Salt Spray Complete; 2,100 hours
- MAP Silico Primer (processed by MAP)
 - Round 1 Pulled at 1,055 hours (Failed Unexpected)
 - Round 2 Started ≈ 1,000 hours

PATTI Pull Adhesion Test Results – Metalast TCP



Primer	Alloy	Panel ID	DFT (mils)	Failure Mode	Pι	III-Off Tensile Strength (psi)	Per	centage Difference	Comments
Hontzon 16709	2024 T2	20907	1.66	60% adhesive/ 10% cohesive / 30% glue		3123		11 01	
Metalast TCP Hentzen 16708 202		20908	1.62	40% adhesive / 20% cohesive / 40% glue		3519		11.91	
Doft 03CN084	2024-T2	21007	1.94	90% adhesive / 10% glue*		2690		2 61	*Test panels were lightly sanded and wiped clean
Deri 0201084	2024-13	21008	1.85	85% adhesive / 15% glue*		2789		3.01	prior to placing the dolly
NAVALCOAT	2024 T2	21107	2.17	60% adhesive / 40% glue		2768		22.52	
NAVALCUAT	2024-13	21108	2.59	10% adhesive / 90% glue		1993		32.33	
	Hentzen 16708 Deft 02GN084	Hentzen 16708 2024-T3 Deft 02GN084 2024-T3	Hentzen 16708 2024-T3 20908 Deft 02GN084 2024-T3 21007 NAVALCOAT 2024-T3 21107	Hentzen 16708 2024-T3 20907 1.66 20908 1.62 Deft 02GN084 2024-T3 21007 1.94 21008 1.85	Hentzen 16708 2024-T3 20907 1.66 60% adhesive / 10% cohesive / 30% glue Deft 02GN084 2024-T3 21007 1.94 90% adhesive / 10% glue* NAVALCOAT 2024-T3 21107 2.17 60% adhesive / 40% glue	Hentzen 16708 2024-T3 20907 1.66 60% adhesive / 10% cohesive / 30% glue 20908 1.62 40% adhesive / 20% cohesive / 40% glue 20908 2024-T3 21007 1.94 90% adhesive / 10% glue* NAVALCOAT 2024-T3 21107 2.17 60% adhesive / 40% glue	Hentzen 16708 2024-T3 20907 1.66 60% adhesive / 10% cohesive / 30% glue 3123 3519 Deft 02GN084 2024-T3 21007 1.94 90% adhesive / 10% glue* 2690 21008 1.85 85% adhesive / 15% glue* 2789	Hentzen 16708 2024-T3 20907 1.66 60% adhesive/ 10% cohesive / 30% glue 3123 20908 1.62 40% adhesive / 20% cohesive / 40% glue 3519 Deft 02GN084 2024-T3 21007 1.94 90% adhesive / 10% glue* 2690 21008 1.85 85% adhesive / 15% glue* 2789	Hentzen 16708 2024-T3 20907 1.66 60% adhesive/ 10% cohesive / 30% glue 3123 3519 11.91 Deft 02GN084 2024-T3 21007 1.94 90% adhesive / 10% glue* 2690 21008 1.85 85% adhesive / 15% glue* 2789 NAVALCOAT 2024-T3 21107 2.17 60% adhesive / 40% glue 2768

20907 21007 21107




PATTI Pull Adhesion Test Results – SurTec 650V



Conversion Coat	Primer	Alloy	Panel ID	DFT (mils)	Failure Mode	Pull-Off Tensile Strength (psi)	Percentage Difference	Comments
SurTec 650V	SurTec 650V Hentzen 16708 2024-T3 21307 2.5		2.5	30% cohesive / 70% glue	3003	9.04		
Surfection Hentzen 16708 20		2024-13	21308	3.31	20% cohesive / 80% glue	3288	3.04	
SurTec 650V	Deft 02GN084	2024 T2	21407	2.03	80% adhesive / 20% glue*	2038	32.35	*Test panels were lightly sanded and wiped clean
3011ec 030V	Derit 02GN064	2024-13	21408	2.01	100% glue*	2826	32.33	prior to placing the dolly
Court of CEOV	NAVALCOAT	2024 T2	21507	2.36	30% adhesive / 70% glue*	3077	2.54	*Test panels were lightly sanded and wiped clean
SurTec 650V	NAVALCOAT	2024-13	21508	1.9	100% adhesive	2970	3.54	prior to placing the dolly


21307 21407 21507




NASA

PATTI Pull Adhesion Test Results – Alodine 5923plus

Conversion Coat	Primer	Alloy	Panel ID	DFT (mils)	Failure Mode	Pull-Off Tensile Strength (psi)	Percentage Difference	Comments
Alodine 5923plus	Hontzon 16700	2024 T2	21707	2.42	33% adhesive / 33% cohesive / 33% glue	2579	19.86	
Alouine 5925pius	Heritzeri 10708	2024-13	21708	2.52	25% cohesive / 75% glue	3148	15.00	
Alodine 5923plus	Doft 03CN084	2024-T2	21807	1.96	95% adhesive / 5% glue*	1032	84.73	*Test panels were lightly sanded and wiped clean
Albume 3923pius	Deri 0201084	2024-13	21808	1.85	95% adhesive / 5% glue*	2554	04.73	prior to placing the dolly
Aladina F022nlus	NAVALCOAT	2024 T2	21907	2.5	100% glue*	3416	16.26	*Test panels were lightly sanded and wiped clean
Alodine 5923plus	NAVALCUAT	2024-13	21908	2.44	100% adhesive	2805	16.36	prior to placing the dolly







PATTI Pull Adhesion Test Results - MAPSIL SILICo Thick


Conversion Coat	Primer	Alloy	Panel ID	DFT (µm)	Failure Mode	Pull-Off Tensile Strength (psi)	Percentage Difference	Comments
MAPSIL®	SILICo	2024-T3	20507	14	100% glue*	616	2.63	*Test panels were lightly sanded and wiped clean
{12 to 16			45% adhesive / 55% glue*	632	2.03	prior to placing the dolly		
MAPSIL®	SILICo	2024-T3	MAP X 7	15	5% adhesive / 95% glue*	876	0.11	*Test panels were lightly sanded and wiped clean
{12 to 16	iμm}	2024-13	MAP X 8	12	100% glue*	950	8.11	prior to placing the dolly

20507

MAP X7







20508





MAP X8







ASTM B 117 Salt Spray Testing

	1st Digit - Scribe Appearance									
0	Bright and clean									
1	Staining, minor corrosion but no build up									
2	Minor/moderate corrosion product build up									
3	Moderate corrosion product build up									
4	Major corrosion product build up									
5	Severe corrosion product build up									

2nc	2nd Digit - Undercutting / Blistering @ Scribe									
0 No lifting of coating										
1	Lifting or loss of adhesion up to 1/16" (2 mm)									
2	Lifting or loss of adhesion up to 1/8" (3 mm)									
3	Lifting or loss of adhesion up to 1/4" (7 mm)									
4	Lifting or loss of adhesion up to 1/2" (13 mm)									
5	Lifting or loss of adhesion beyond 1/2" (>13 mm)									

	Size - 3rd Digit - Blistering Away from the Scribe
0 = None	Frequency
1 = Very Small up to 1/16" (2 mm)	F = Few
2 = Small up to 1/8" (3 mm)	M = Medium
3 = Small to Medium up to 1/4" (7 mm)	MD = Med. Dense
4 = Medium to Large up to 1/2" (13 mm)	D = Dense
5 = Large (>13 mm)	



Deft 02GN084 2024-T3 21405

NAVALCOAT

21504

21505

SurTec 650V

SurTec 650V

ASTM B 117 Salt Spray Testing



									Evalu	iation 4	- 2,100 hours of exposure					
1	1st Digit - Scribe Appearance 2nd Digit - Undercutting / Blistering @ Scribe Size - 3rd Digit - Blistering Away from the Scribe															
0	Bright and clear	า			0	No lifting	of coating	g		0 = None Frequency						
1	Staining, minor	corrosion	but no bu	ild up	1	Lifting or	loss of ac	lhesion up	to 1/16" (2 mm)						
2	Minor/moderate	corrosio	n product	build up	2	Lifting or	loss of ac	lhesion up	to 1/8" (3	mm)	mm) 2 = Small up to 1/8" (3 mm) M = Medium					
3	Moderate corro	sion produ	uct build u	р	3	Lifting or	loss of ac	lhesion up	to 1/4" (7	mm)	3 = Small to Medium up to 1/4" (7 mm)	MD = Med. Dense				
4	Major corrosion	product b	ouild up		4	Lifting or	loss of ac	lhesion up	to 1/2" (1	3 mm)	4 = Medium to Large up to 1/2" (13 mm)	D = Dense				
5	Severe corrosion	n product	build up		5	Lifting or	loss of ac	lhesion be	eyond 1/2"	(>13 mm)	5 = Large (>13 mm)					
Conversion Coat	Primer	Alloy	Panel ID	1st Digit	2nd	Digit		3rd Digit				Notes - Comments				
Conversion Coat	Filliei	Alloy	railerib	Scribe	Reading	Isolated	Size	Freq	Isolated			Notes - Comments				
			20904	3	0	N/A	1	MD	Yes	Blistering - top half of test panel; not edge effect; could be coating thickness issue						
Metalast TCP	Hentzen 16708	2024-T3	20905	3	0	N/A	1	MD	Yes		Blistering - top half of test panel; not edge effect; could be coating thickness issue					
			20906	4	0	N/A	1	M	Yes		Blistering - top half of test panel; not edge effect; could be coating thickness issue					
	•															
			21104	3	1	No	2	F	Yes	Blistering - bottom right corner. not edge effect; could be coating thickness issue						
Metalast TCP	Deft 02GN084	2024-T3	21005	3	0	N/A	2	F	Yes		Blistering - very	top of panel; not edge effect; could be coating thickness issue				
			21006	3	1	No	0	N/A	N/A							
			21004	3	0	N/A	1	MD	No	Blister	. , .	he scribe but does not appear to be undercuttering. Blisters formed at the top edge of the panel. In removed from some of the blisters exposing bare aluminum.				
Metalast TCP	NAVALCOAT	2024-T3	21105	3	0	N/A	2	MD	No		. , ,	e scribe but does not appear to be undercuttering. A few blisters are located on the top half of the as well as along the right edge and bottom corners. Coating has been removed from some of the blisters exposing bare aluminum.				
			21106	3	0	N/A	2	MD	No		. , ,	e scribe but does not appear to be undercuttering. A few blisters are located on the top half of the is well as the bottom corners. Coating has been removed from some of the blisters exposing bare aluminum.				
Conversion Coat	Primer	Alloy	Panel ID	1st Digit		Digit		3rd Digit				Notes - Comments				
				Scribe	Reading	Isolated	Size	Freq	Isolated	ed						
			21304	3	2	No	0	N/A	N/A	,						
SurTec 650V	Hentzen 16708	2024-T3	21305	3	2	No	0	N/A		N/A						
	<u> </u>		21306	3	2	No	0	N/A	N/A	A						
		1						1	1							
		l	21404	3	2	No	0	N/A	N/A							

1 blister found on the top half of the panel, could be aggregate

1 blister found on the bottom half of the panel, could be aggregate. Blistering on lower right corner.

3 pits on lower left side away from the scribe, 1 one very close to the edge. 2 blisters were found away from the scribe. Blisters on bottom corners and along the top edge. Coating has been removed from some of the blisters exposing bare aluminum.

N/A

N/A

F

N/A

Yes

No

N/A

0





ASTM B 117 Salt Spray Testing

									Evalu	ation 4	- 2,100 hours of exposure			
1	st Digit - Scribe	Appeara	nce		2nc	l Digit - Ur	dercutti	ng / Bliste			, 11 10 10 10 10 10 10 10 10 10 10 10 10	Size - 3rd Digit - Blistering Away from the Scribe		
0	Bright and clear	1			0	No lifting	of coatin	g			0 = None	Frequency		
1	Staining, minor	corrosion	but no bui	ld up	1	Lifting or	loss of ac	lhesion up	to 1/16" (2 mm)	1 = Very Small up to 1/16" (2 mm)	F = Few		
2	Minor/moderate	corrosio	n product	build up	2	Lifting or	loss of ac	lhesion up	to 1/8" (3	mm)	2 = Small up to 1/8" (3 mm)	M = Medium		
3	Moderate corros	sion produ	ıct build u	р	3	Lifting or	loss of ac	lhesion up	to 1/4" (7	mm)	3 = Small to Medium up to 1/4" (7 mm)	MD = Med. Dense		
4	Major corrosion	product b	uild up		4	Lifting or	loss of ac	lhesion up	to 1/2" (1	3 mm)	4 = Medium to Large up to 1/2" (13 mm)	D = Dense		
5	Severe corrosion	n product	build up		5	Lifting or	loss of ac	lhesion be	yond 1/2"	(>13 mm)	5 = Large (>13 mm)			
Conversion Coat	Primer	Alloy	Panel ID	1st Digit		Digit	Size	3rd Digit			Notes - Comments			
			21704	Scribe	Reading 0	Isolated N/A	Size	Freq	Isolated Yes		1 blisted found at the top right edge of the panel			
Alodine 5923plus	Hentzen 16708	2024-T3	21704	1	0	N/A N/A	1	F	Yes		_			
Aloume 3323pius	1101112011 10700	2024-13	21703	1	0	N/A	1	-	Yes		1 blister at the top center edge of the panel 2 blisters at the top right edge of the panel			
			21700	1		IN/A	1	<u> </u>	163			Z bilisters at the top right edge of the panel		
			21804	3	1	Yes	0	N/A	N/A					
Alodine 5923plus	Deft 02GN084	2024-T3	21805	3	1	Yes	0	N/A	N/A					
			21806	3	1	Yes	0	N/A	N/A					
								<u> </u>	<u>, , , , , , , , , , , , , , , , , , , </u>					
			21904	3	0	N/A	0	N/A	N/A		Blis	stering / coating removal on bottom edge / corners		
Alodine 5923plus	NAVALCOAT	2024-T3	21905	3	0	N/A	0	N/A	N/A		Blis	stering / coating removal on bottom edge / corners		
			21906	3	0	N/A	0	N/A	N/A			Blistering on bottom edge / corners		
Conversion Coat	Primer	Alloy	Panel ID	1st Digit	2nd	Digit		3rd Digit				Notes - Comments		
conversion cour		707		Scribe	Reading	Isolated	Size	Freq	Isolated					
MAPSIL®	SILICo		20501									PULLED FROM TESTING AFTER 1,055 HOURS		
{12 to 1	6 μm}	2024-T3	20502									PULLED FROM TESTING AFTER 1,055 HOURS		
,			20503							PULLED FROM TESTING AFTER 1,055 HOURS				
				1	1	1			1					
MAPSIL®	SILICo		MAP X 1									PULLED FROM TESTING AFTER 1,055 HOURS		
{12 to 1	6 μm}	2024-T3	MAP X 2		1			1				PULLED FROM TESTING AFTER 1,055 HOURS		
•			MAP X 3									PULLED FROM TESTING AFTER 1,055 HOURS		



ASTM B 117 Salt Spray Testing

Metalast TCP

Conversion Coat	Primer	Allov	Panel ID	1st Digit	2nd	3rd Digit			
Conversion Coat	Pilillei	Alloy	Pallel ID	Scribe	Reading	Isolated	Size	Freq	Isolated
Metalast TCP		2024-T3	20904	3	0	N/A	1	MD	Yes
	Hentzen 16708		20905	3	0	N/A	1	MD	Yes
			20906	4	0	N/A	1	М	Yes

Conversion Coat	Primer	Alloy	Panel ID	1st Digit	2nd	3rd Digit			
	Pilillei	Alloy	Pallel ID	Scribe	Reading	Isolated	Size	Freq	Isolated
			21104	3	1	No	2	F	Yes
Metalast TCP	Deft 02GN084	2024-T3	21005	3	0	N/A	2	F	Yes
			21006	3	1	No	0	N/A	N/A

Conversion Coat	Primer	Alloy	Panel ID	1st Digit	2nd	Digit		3rd D	igit
Conversion Coat	Pilillei	Alloy	Pallel ID	Scribe	Reading	Isolated	Size	Freq	Isolated
			21004	3	0	N/A	1	MD	No
Metalast TCP	NAVALCOAT	2024-T3	21105	3	0	N/A	2	MD	No
			21106	3	0	N/A	2	MD	3 <u>4</u> 0



ASTM B 117 Salt Spray Testing SurTec 650V

Conversion Coat	Primer	Alloy	Panel ID	1st Digit	2nd Digit		3rd Digit		
				Scribe	Reading	Isolated	Size	Freq	Isolated
SurTec 650V	Hentzen 16708		21304	3	2	No	0	N/A	N/A
		2024-T3	21305	305 3 2 No 0 N	N/A	N/A			
			21306	3	2	No	0	N/A	N/A

Conversion Coat	Primer	Alloy	Panel ID	1st Digit	2nd Digit		3rd Digit		
				Scribe	Reading	Isolated	Size	Freq	Isolated
SurTec 650V	Deft 02GN084	2024-T3	21404	3	2	No	0	N/A	N/A
			21405	3	1	No	0	N/A	N/A
			21406	3	1	No	0	N/A	N/A

Conversion Coat	Primer	Alloy	Panel ID	1st Digit	2nd Digit		3rd Digit		
				Scribe	Reading	Isolated	Size	Freq	Isolated
SurTec 650V	NAVALCOAT		21504	3	0	N/A	1	F	Yes
		2024-T3	21505	3	0	N/A	1	F	Yes
			21506	3	0	N/A	1	F	No



ASTM B 117 Salt Spray Testing Alodine 5923plus

Conversion Coat	Primer	Alloy	Panel ID	1st Digit	2nd	Digit	3rd Digit		
Conversion Coat	riiilei	Alloy	Pallel ID	Scribe	Reading	Isolated	Size	Freq	Isolated
	Hentzen 16708	2024-T3	21704	1	0	N/A	1	F	Yes
Alodine 5923plus			21705	1	0	N/A	1	F	Yes
			21706	1	0	N/A	1	F	Yes

Conversion Coat	Primer	Alloy	Panel ID	1st Digit	2nd	Digit	3rd Digit		
Conversion Coat	riiiiei	Alloy	Pallel ID	Scribe	Reading	Isolated	Size	Freq	Isolated
	Deft 02GN084	2024-T3	21804	3	1	Yes	0	N/A	N/A
Alodine 5923plus			21805	3	1	Yes	0	N/A	N/A
			21806	3	1	Yes	0	N/A	N/A


Conversion Coat	Primer	Alloy	Panel ID	1st Digit	2nd	3rd Digit			
Conversion Coat	Primer	Alloy	Pallel ID	Scribe	Reading	Isolated	Size	Freq	Isolated
	NAVALCOAT	2024-T3	21904	3	0	N/A	0	N/A	N/A
Alodine 5923plus			21905	3	0	N/A	0	N/A	N/A
			21906	3	0	N/A	0	N/A	N/A




Test Panel Evaluation Chrome Free Conversion Coatings with MAPSIL SILICo AS MAPSIL SILICo {Thick}

PATTI Pull Adhesion Test Results – Metalast TCP

Conversion Coat	Primer	Alloy	Panel ID	DFT (um)	Piston	Burst Pressure (psi)	Failure Mode I	'till	-Off Tensile Strength (psi)			
			21207	62	F-4	40.5	100% glue		835			
Metalast TCP	MAPSIL SILICo AS	2024-T3				45.9	100% glue		947			
						10.5	100% glue		215			
Wetalast ICF			21208	57	F-4	28.1	100% glue		579			
						12.1	100% glue		248			
						46.3	100% glue		955			







NASA

PATTI Pull Adhesion Test Results – Metalast TCP

Primer	Alloy	Panel ID	DFT (um)	Piston	Burst Pressure (psi)	Failure Mode	Pull-Off Tensile Strength (psi)
					9.3	100% glue	191
l	'	MS107	19	F-4	34.9	100% glue	719
MADCH CHIC	2024 T2				44.6	100% glue	920
MAPSIL SILICO	2024-13				45.0	100% glue	928
l	'	MS108	19	F-4	46.0	100% glue	949
	<u> </u>				9.6	100% glue	197
			MS107 MAPSIL SILICo 2024-T3	MS107 19 MAPSIL SILICo 2024-T3	MS107 19 F-4 MAPSIL SILICo 2024-T3	MS107 19 F-4 9.3 MS107 19 F-4 34.9 44.6 MS108 19 F-4 46.0	MAPSIL SILICo MS107 19 F-4 9.3 100% glue 34.9 100% glue 44.6 100% glue 45.0 100% glue 45.0 100% glue 45.0 100% glue


MS 107 MS 108






PATTI Pull Adhesion Test Results – SurTec 650V

Conversion Coat	Primer	Alloy	Panel ID	DFT (um)	Piston	Burst Pressure (psi)	Failure Mode	Pull-Off Tensile Strength (psi)
	MAPSIL SILICo AS			65	F-4	17.9	20% adhesive / 80% glue	368
			21607			50.8	100% glue	1048
SurTec 650V		2024-T3				47.7	100% glue	984
3th 1ec 050 v			21608	66	F-4	17.9	100% glue	368
						17.5	100% glue	360
						43.8	100% glue	903







PATTI Pull Adhesion Test Results – SurTec 650V

Conversion Coat	Primer	Alloy	Panel ID	DFT (um)	Piston	Burst Pressure (psi)	Failure Mode	Pull-Off Tensile Strength (psi)
				24		44.7	100% glue	922
		'	MS115		F-4	47.1	100% glue	971
SurTec 650V	MAPSIL SILICo	2024-T3				44.2	100% glue	912
Sui 160 050 V	MAF SIL SILICO	2024-13				35.6	100% glue	734
		'	MS116	22	F-4	33.9	100% glue	699
		1 '				10.3	100% glue	211






MS 116






PATTI Pull Adhesion Test Results – Alodine 5923plus

Primer	Alloy	Panel ID	DFT (um)	Piston	Burst Pressure (psi)	Failure Mode	Pull-Off Tensile Strength (psi)
		22007			46.6	100% glue	961
1	'		61	F-4	58.3	100% glue	1203
MAPSIL SILICo AS	2024 T3			<u> </u>	27.0	100% glue	556
	2024-13				46.5	100% glue	959
1	'	22008	61	F-4	45.8	100% glue	945
	<u> </u>			<u> </u>	42.7	100% glue	881
			MAPSIL SILICo AS 2024-T3	MAPSIL SILICo AS 2024-T3 22007 61	22007 61 F-4 MAPSIL SILICo AS 2024-T3	MAPSIL SILICo AS 2024-T3 22007 61 F-4 46.6 58.3 27.0 46.5 46.5 45.8	MAPSIL SILICo AS 2024-T3 22007 61 F-4 46.6 100% glue 27.0 100% glue 27.0 100% glue 46.5 100% glue 27.0 100% glu







PATTI Pull Adhesion Test Results – Alodine 5923plus



Conversion Coat	Primer	Alloy	Panel ID	DFT (um)	Piston	Burst Pressure (psi)	Failure Mode	Pull-Off Tensile Strength (psi)
Al-Jin- 5022-k	MAPSIL SILICo	2024-T3	MS123	20		46.8	100% glue	965
					F-4	50.2	100% glue	1036
						33.0	100% glue	680
Alodine 5923plus			MS124	17	F-4	50.5	100% glue	1042
						44.8	100% glue	924
						42.7	100% glue	881







Phase® ESA/NASA

Pretreat+Primer

Alodine1200S+ PR (NASAControl)Iridite14-2+ PR (ESAControl)Metalast+ PR1 (NASACAlternativeMAPCSilico+ PR2 (NASACAlternativeAlodine5923Plus+ PR3 (ESACAlternativeSurTec50V+ PR4 (ESACAlternative

Substrates:

- 2024-T3
- 2024-T8
- 6061-T6
- 7075-T6
- 7075-T73

Testing:

- B117 Salt Fog
- Atmospheric Exposure
- Adhesion X-Cut Tape
- Adhesion PATTI Jr.



Phase B ESA/NASA

Pretreat+Primer+Topcoat

Alo	dine1200S	+	PR	+	TC	(NASAIControl)
Irid	ite 1 4-2	+	PR	+	TC	(ESA©Control)
Me	talast <arri>TCP</arri>	+	PR1	+	TC	(NASA Alternative 1)
MA	.P ∄ ilico	+	PR2	+	TC	(NASA@Alternative@2)
Alo	dine55923Plus	+	PR3	+	TC	(ESABAlternative11)
Sur	Tec 5 50V	+	PR4	+	TC	(ESA Alternative 22)

Substrates:

- 2024-T3
- 2024-T8
- 6061-T6
- 7075-T6
- 7075-T73

Testing:

- B117 Salt Fog
- Atmospheric Exposure
- Adhesion X-Cut Tape
- Adhesion PATTI Jr.





Matt Rothgeb matthew.j.rothgeb@nasa.gov (321) 867-8476

Kurt Kessel kurt.r.kessel@nasa.gov (321) 867-8480



